




TECHNICAL SPECIFICATIONS
QUALITY LABORATORY
MODEL
45X45 FS-2
BODY TYPE
FLOOR TILES GROUP BIIa

| Body Technical Specifications | | Test Method | Standard Value | Pass/Fail |
|---|--|---|----------------|-----------|
|  Length and width | |  | ± 0.6 % | Yes |
| | | | ± 5 % | Yes |
| | | | ± 0.5 % | Yes |
| | | | ± 0.5 % | Yes |
| | | | ± 0.5 % | |
|  Water absorption | |  | 3<AA<6 % | Yes |
|  Breaking strength | |  | >1100 N | Yes |
| | | | >22 N/mm² | Yes |
|  Frost resistance | |  | NOT RESIST | Yes |
|  Linear thermal expansion coefficient | |  | 9*10^-6 K^-1 | Yes |

| Surface Technical Specifications | | Test Method | Standard Value | Pass/Fail |
|--|--|---|----------------|-----------|
|  Slipperiness | | DIN-51130 | R9 | Yes |
| | | UNE-ENV-12633 | CLASS 1 | Yes |
|  Surface abrasion resistance (PEI) | |  | 4 | Yes |
|  Deep abrasion resistance | |  | - | - |
|  Surface hardness (MOHS scale) | | EN-101 | 6 | Yes |
|  Acids and alkalis resistance | |  | GLA/GLA | Yes |
|  Crazing resistance | |  | RESIST | Yes |
|  Staining resistance | |  | 5 | Yes |
|  Surface Quality | |  | > 95 % | Yes |

GOODS ARE IN CONFORMITY WITH ISO 13006 STANDARDS


 Avenida Manuel Escobedo, 26
 33002 Gijón (Asturias) España
Head of Laboratory